



## Effect of Landfill Leachate on Groundwater Contamination: A case study of Obio-Akpo Local Government Area, Rivers State, Nigeria

GOLDEN, AH; \*INICHINBIA, S

*Department of Physics, University of Port Harcourt, Port Harcourt, Nigeria*

*\*Corresponding Author Email: [sonny.inichinbia@yahoo.com](mailto:sonny.inichinbia@yahoo.com), [sonny.inichinbia@uniport.edu.ng](mailto:sonny.inichinbia@uniport.edu.ng)*

**ABSTRACT:** This research investigates the effect of landfill leachate on the groundwater in "Odum", a community that plays host to a dumpsite along Choba/Alakahia road in Obio/Akpor Local Government Area (L.G.A.) of Rivers State, Nigeria. Five vertical electrical soundings (VES) were conducted using the Schlumberger configuration and also five horizontal profiling were done using the Wenner configuration. The field data were acquired using ABEM terrameter SAS 300C, and processed using the IP TWO WAY software. The results showed that the area is composed of sandstone, clay, laterite, sandy clay, and sand. Also, from careful analysis and interpretation of the processed data it was observed that contaminated zones have low resistivity (high conductivity). Strikingly, areas of low resistivity such as 11.9  $\Omega\text{m}$  and others with high resistivity up to greater than 1818  $\Omega\text{m}$  do exist. The results show that groundwater around this landfill contaminated area contains highly conductive leachates like sulphur, methane, ammonia gas at depths > 16 m. This indicates that the study area is not a good aquifer zone.

**DOI:** <https://dx.doi.org/10.4314/jasem.v24i8.10>

**Copyright:** Copyright © 2020 Golden and Inichinbia. This is an open access article distributed under the Creative Commons Attribution License (CCL), which permits unrestricted use, distribution, and reproduction in any medium, provided the original work is properly cited.

**Dates:** Received: 30 May 2020; Revised: 03 July 2020; Accepted: 05 August 2020

**Keywords:** Resistivity, Landfill, Leachate, Groundwater, Dumpsite, Aquifer, Sounding

Several works have been done on different dumpsites in many parts of the world, and also, in Nigeria that show how the quality of groundwater and human health is affected by leachate percolation into underground water bodies. Such works, among others include those of Udom and Esu 2004; Udom *et al.* 1999; Rosqvist *et al.* 2003; Ibe and Njoku 1999; Inichinbia and Sule 2018a; Inichinbia and Sule 2018b; Olayinka and Olayiwole 2000; Ehirim *et al.* 2009a; Ehirim *et al.* 2009b; Adebibu, 1985; Agbemuko *et al.* 2017; Ajadike 2007; Ige and Ogunsanwo 2009; Adekunle and Kehinde 2008; Eshimiakhe *et al.* (2019). The total amount of water in the earth is virtually constant but its distribution over time and space varies to a great extent. Wherever people live, they must have a clean and continuous supply of water as a primary requirement for human existence. The assessment of the quality, supply and renewal of water is quite a well-known problem, but it is becoming critical with the growth of population and rapid industrialization. The rising population of Nigeria of about 180 million requires knowledge of the proper disposal of wastes. This is because wastes are dumped recklessly with little environmental regards in major cities of many states in Nigeria including Rivers State. Increase in population, changes or improvement in wages, massive expansion of the urban areas and the changing lifestyle or better standard of living, as well as improvement in technology in Nigeria has

encouraged solid waste generation. Although solid waste is an asset when properly managed, its volume has continued to increase tremendously in recent times. In Nigeria, much has been, and is still being invested on municipal solid waste management in cities. But little progress has been made because of severe financial, technological and institutional constraints within the public and the private sectors. Waste could be defined as any material lacking direct value to the producer and so must be disposed of. Similarly, waste is any material that is thrown away as unwanted material. The term "solid waste" means any garbage, refuse, or sludge from a waste treatment plant, water supply treatment plant, or air pollution control facility and other discarded materials, including solid, liquid, semi-solid, industries, mining etc. Solid waste can however be classified into different types, depending on their source; household waste is generally classified as municipal waste; industrial waste as hazardous waste, and biomedical waste or hospital waste as infectious waste. The trend of indiscriminate or uncontrolled and haphazard construction of groundwater facilities particularly shallow wells and boreholes in the residential areas close to refuse dumpsites is of great health concern, as this may contribute significantly to groundwater pollution. This results to an adverse impact on the aquifer as a result of overdependence and over abstraction with attendant negative effects. The Odum

*\*Corresponding Author Email: [sonny.inichinbia@yahoo.com](mailto:sonny.inichinbia@yahoo.com), [sonny.inichinbia@uniport.edu.ng](mailto:sonny.inichinbia@uniport.edu.ng)*



points ranging from 15.00 m to greater than 30.00 m, between 45.00m and 50.00 m, and 75.00 m to greater than 95.00 m (> 65.00 m). The zone of low resistivity (50.20 Ωm) at the upper part of the inverse model resistivity section could be associated with highly conductive leachate, since contaminant plume originating from the decomposition of the various wastes dumped on the site has seeped into the aquifer and possibly caused the contamination of the surrounding soil too. The upper zone and layers have decreasing resistivity (green to yellow) with resistivity

ranging from 103.00 Ωm – 170.00 Ωm at depths ranging from 6.30 m to a depth greater than 16 m and at surface points ranging from 15.00 m to greater than 95.00 m (>80.00 m). These layers are permeable sand Formation of varying grain sizes, thicknesses and moisture contents (Tamuno and Inichinbia, 2019; Eshimiakhe *et al.*, 2019). This site is no longer has a good aquifer zone because of the impact of the leachate from the dumpsite.




Fig 2. Inverse model resistivity section of profile 1. The model is the result of the simultaneously processed horizontal profiling and vertical profiling data.




Fig 3. Inverse resistivity model section of profile 2. The section is the result of the simultaneously processed horizontal profiling and vertical profiling

From the results of the 2D resistivity imaging it is clear that the top soil and groundwater around the landfill site to depth exceeding 16m which is within the

aquifer in the study area, have been contaminated by the leachate. The results of the 2D resistivity imaging isolated three zones in each profile mapped around the

landfill site. These are the zones of anomalously low resistivity which are regarded as highly conductive leachate contaminated zones and contain pathogens that causes health problems. Secondly, a zone of anomalously high resistivity as fill wastes and thirdly, a zone of increasing resistivity layers which is interpreted as permeable sandy formation of varying grain sizes, thicknesses and moisture contents.

Hydrogeological features of the study area show that leachate derived from the landfill sites seeps into the vulnerable sand aquifer and hence contaminates the groundwater. This research project has demonstrated

that 2D resistivity imaging can be used to investigate pollutions of top soils and groundwater as well as the lateral extents of the contamination of the leachate plumes from the waste (medical, domestic and industrial) disposal area.

Table 1 shows the interpretation of the processed field data for VES obtained at Olobo environs of Choba/Alakahia and revealed five (5) geoelectric layers of resistivity values ranging from 47.10  $\Omega\text{m}$  – 148.30  $\Omega\text{m}$  and depth to the layers also ranging from 1.95 m – 35.28 m. the resistivity of layers of depth and thickness beyond 35.28 m had poor resolution.

**Table 1.** Interpretation of processed VES data 2

No of layers	RES (R $\Omega$ )	Depth (m)	Thickness (m)	Lithological Unit
1.	47.10	1.95	1.95	Top Soil
2.	78.95	4.75	2.80	Sand Stone, laterite
3.	166.20	13.59	8.85	Clay/Sandy
4.	248.60	35.28	21.69	Coarse, Weak Aquifer
5.	148.30	-	-	Indurate

**Conclusion:** Dumping of waste (domestic, industrial, and medical) in urban or rural settlements without environmental precautions leads to serious health issues. Quality water management is an issue that must be given top priority in our state and country. The hydrogeological features of the vulnerable sandy aquifer are not suitable for waste disposal as contaminants easily seep into the groundwater. Therefore construction of landfill sites must include solutions to landfill problems, such as thick concrete floor, bagging waste in waterproof bags, creating public awareness and immediate recycling.

**Acknowledgements:** The authors are thankful to Adekunle Sofolabo for his assistance and all others in the Department of Physics who contributed in no small measure to the completion of this work.

## REFERENCES

- Abul Salam (2010). Environmental and Health Impact of Solid Waste Disposal at Mangaweni dumpsite in Manzini Swaziland. *J. of sustainable Dev. in Africa*. 12(7): 1509 - 5520.
- Adebibu, EA (1985). Quality Assessment of Groundwater in the vicinity of dumpsites in Lagos, Nigeria. *J. of appl. Sci.* 2(1): 39-44
- Adekunle, A; Kehinde IT (2008). Impact of Industrial effluents on quality of segment of Asa River within and industrial estate in Ilorin Nigeria. *NY sci. j.* 1(1): 17-21.
- Agbemuko, OS; Tamunobereton-Ari, I; Ngah, SA (2017). Determination of the effects of dumpsites on aquifer at Port Harcourt metropolis, Rivers State, Nigeria. *IOSR-J. of Appl. Phys.* 9(6): ver. I, 41 – 54.
- Ajadike, AT (2007). Waste Management towards Sustainable Development in Nigeria. A Case Study of Lagos State, Nigeria. *Int.NGO J.* 4(4): 173-179.
- Ehirim, CN; Ebeniro, JO; Ogbu, DA (2009a). A geophysical and Hydro-physiochemical impact of a solid Waste Landfill in Port Harcourt municipality, Nigeria. *Pac. J. of Sci. and Technol.* 10: 596 - 603.
- Ehirim, CN; Ebeniro, JO; Olanegan, OP (2009b). A geophysical investigation of solid waste landfill, using 2-D Port Harcourt municipality, Rivers state, Nigeria. *Pac. J. of Sci. Technol.* 10: 604 - 613.
- El Mahmoudi (2010). Application of Resistivity method in environmental study of appearance of soil water in central of Tenth of Ramadan city, Egypt. *Quarterly J. of Eng. Geol. and Hydrogeol.* 43(2): 171-184
- Esakuku, S; Palamuelu, K; Kuraian J (2003). Assessment of heavy metals in municipal solid wastes dumpsite workshop on sustainable landfill management, Chennai, India, 139-145
- Eshimiakhe, D; Jimoh, R; Musa, Z (2019). Two-dimensional image of seismic refraction tomography and electrical resistivity tomography survey in a proposed geophysical test site at

- Shika, Ahmadu Bello University Zaria, Nigeria. *Global J. of Earth and Environ. Sci.* 4(4): 56 – 66.
- Ibe, KM; Njoku, JC (1999). Migration of contaminants in groundwater at a landfill site in Owerri, South East, Nigeria. *J. of Environ. Hydrol.* 7(8): 1 – 9
- Ige, OO; Ogunsawo, O (2009). Environmental geological assessment of a solid waste disposal site Ilorin southwestern Nigeria. *Nat. and sci.* 7(9): 53-62.
- Inichinbia, S; Sule, PO (2018a). Evaluation of the layering of rock strata and basement rock depth of a university teaching hospital premises in northern Nigeria. *J. of Appl. Sci. and Environ. Manage.* 22 (4): 597 – 603
- Inichinbia, S; Sule, PO (2018b). 2D geo-electrical imaging for groundwater exploration in Shika, along Zaria-Funtua road north of Ahmadu Bello University main campus, Samaru, Zaria. *J. of Appl. Sci. and Environ. Manage.* 22 (4): 609 – 612
- Loizidou, M; Kapantamos (1993). Effect of leachate from landfill on underground water quality. *Sci total environ.* 128 (1): 69-81
- Olayinka, AI; Olayiwola, MA (2000). Integrated use of Geophysical imaging and hydro-chemical Methods in delineating limit of polluted surface and groundwater at a landfill site in Ibadan Area, S.W Nigeria. *J. of Mining and Geol.* 37(1): 193 - 198.
- Rosqvist, H; Dahlin, T; Fourie, A; Rohrs, L; Bengtseeon, A; Larsson, M (2003). Mapping of Leachate plumes at two landfill sites in South Africa Geoelectrical Imaging Techniques. *Proceedings of 9<sup>th</sup> Int. Waste Manage. Landfill Symp.* Cagliari, Italy. 1 – 10
- Sirhan, A; Hamidi, M; Anderieux, P (2011). Electrical Resistivity Tomography, an Assessment Tool for Water Resource: *Al-Aroub Basin, West Bank, Palestine Asian J. of Earth Sci.* 4(1): 38-45.
- Tamuno, W; Inichinbia, S (2019). Vertical Electric Sounding of Leachate Contaminant Plumes at a Dumpsite in Obigbo, Rivers State, Nigeria. *J. Appl. Sci. Environ. Manage.* 23(12): 2245-2249
- . Udom, GJ; su, EO (2004). A preliminary Assessment of the Impact of Solid Wastes on Soil and Groundwater System in Parts of Port Harcourt city and its environs, Rivers State, Nigeria. *Global J. of Environ. Sci.* 4(1): 234 – 239
- Udom, GJ; EtuEfeator, JO; Esu, EO (1999). Hydrogeochemical of Groundwater in part of Port Harcourt and Tai Eleme Local Government Area, Rivers State. *Global J. Pure Appl. Sci.* 5: 545 – 551